

FCC Supplier's Declaration of Conformity

Importer Name: Dahua Technology USA Inc.

Importer Address: 23 Hubble Irvine, CA 92618

Equipment

Product Name: **IPC**

Model No.:

DH-IPC-HDBW7442HP-Z;DH-IPC-HDBW7442HN-Z;IPC-HDBW7442HP-Z;IPC-HDBW7442HN-Z;DH-IPC-HDBW7442H-Z;IPC-HDBW7442H-Z;IPC-HDBW7241H-Z-27135-DC12AC24V;DH-IPC-HDBW7442HP-Z4;DH-IPC-HDBW7442HN-Z4;IPC-HDBW7442HP-Z4;IPC-HDBW7442HN-Z4;DH-IPC-HDBW7442H-Z4;IPC-HDBW7442H-Z4;DH-IPC-HDBW7241HP-Z;DH-IPC-HDBW7241HN-Z;IPC-HDBW7241HP-Z;IPC-HDBW7241HN-Z;DH-IPC-HDBW7241H-Z;IPC-HDBW7241H-Z;IPC-HDBW7442H-Z-2712-DC12AC24V;IPC-HDBW7442H-ZE-2712-DC12AC24V;DH-IPC-HDBW7442HP-ZFR;DH-IPC-HDBW7442HN-ZFR;IPC-HDBW7442HP-ZFR;IPC-HDBW7442HN-ZFR;DH-IPC-HDBW7442H-ZFR;IPC-HDBW7442H-ZFR;IPC-HDBW7442H-ZEFR-2712-DC12AC24V;DH-IPC-HDBW7442HP-Z4FR;DH-IPC-HDBW7442HN-Z4FR;IPC-HDBW7442HP-Z4FR;IPC-HDBW7442HN-Z4FR;DH-IPC-HDBW7442H-Z4FR;IPC-HDBW7442H-Z4FR;DH-IPC-HDBW7241HP-Z5;DH-IPC-HDBW7241HN-Z5;IPC-HDBW7241HP-Z5;IPC-HDBW7241HN-Z5;DH-IPC-HDBW7241H-Z5;IPC-HDBW7241H-Z5;IPC-HDBW7241H-Z5-0735-DC12AC24V;IPC-HDBW7241H-Z5E-0735-DC12AC24V;DH-IPC-HDBW7842HP-Z;DH-IPC-HDBW7842HN-Z;IPC-HDBW7842HP-Z;IPC-HDBW7842HN-Z;DH-IPC-HDBW7842H-Z;IPC-HDBW7842H-Z;IPC-HDBW7842H-Z-2712-DC12AC24V;IPC-HDBW7842H-ZE-2712-DC12AC24V;DH-IPC-HDBW5842HP-ZHE;DH-IPC-HDBW5842HN-ZHE;IPC-HDBW5842HP-ZHE;IPC-HDBW5842HN-ZHE;DH-IPC-HDBW5842H-ZHE;IPC-HDBW5842H-ZHE;N85DV7Z;IPC-HDBW5842H-ZEH-2712F-DC12AC24V;IPC-HDBW5842H-ZEH-2712-DC12AC24V;IPC-HDBW5842H-ZEH-2712;DH-IPC-HDBW7842HP-Z4;DH-IPC-HDBW7842HN-Z4;IPC-HDBW7842HP-Z4;IPC-HDBW7842HN-Z4;DH-IPC-HDBW7842H-Z4;IPC-HDBW7842H-Z4;DH-IPC-HDBW5842HP-Z4HE;DH-IPC-HDBW5842HN-Z4HE;IPC-HDBW5842HP-Z4HE;IPC-HDBW5842HN-Z4HE;DH-IPC-HDBW5842H-Z4HE;IPC-HDBW5842H-Z4HE;DH-IPC-HDBW7842HP-Z4;DH-IPC-HDBW7842HN-Z4;IPC-HDBW7842HP-Z4;IPC-HDBW7842HN-Z4;DH-IPC-HDBW7842H-Z4;IPC-HDBW7842H-Z4;DH-IPC-HDBW5842HP-Z4HE;DH-IPC-HDBW5842HN-Z4HE;IPC-HDBW5842HP-Z4HE;IPC-HDBW5842HN-Z4HE;DH-IPC-HDBW5842H-Z4HE;IPC-HDBW5842H-Z4HE;IPC-HDBW7442H-Z-2712F-DC12AC24V;IPC-HDBW7442H-ZE-2712F-DC12AC24V;IPC-HDBW7442H-ZEH-2712;IPC-HDBW7442H-Z-2712;IPC-HDBW7442H-Z4-0832-DC12AC24V;IPC-HDBW7442H-Z4E-0832-DC12AC24V;IPC-HDBW7442H-Z4EH-0832-DC12AC24V;IPC-HDBW7442H-Z4-0832;IPC-HDBW7842H-Z-2712F-DC12AC24V;IPC-HDBW7842H-ZE-2712F-DC12AC24V;IPC-HDBW7842H-ZEH-2712;IPC-HDBW7842H-Z-2712;IPC-HDBW7442H-ZFR-2712F-DC12AC24V;IPC-HDBW7442H-ZFR-2712-

DC12AC24V;IPC-HDBW7442H-ZFR-2712;IPC-HDBW7442H-Z4FR-0832-DC12AC24V;IPC-HDBW7442H-Z4FR-0832;IPC-HDBW7842H-Z4-0832-DC12AC24V;IPC-HDBW7842H-Z4EH-0832-DC12AC24V;IPC-HDBW7842H-Z4HE-0832-DC12AC24V;IPC-HDBW7842H-Z4E-0832;IPC-HDBW5842H-Z4E-0832-DC12AC24V;IPC-HDBW5842H-Z4EH-0832-DC12AC24V;IPC-HDBW5842H-Z4HE-0832-DC12AC24V;IPC-HDBW5842H-Z4E-0832;N87DV6Z;

Trade Name: 

Telephone. : (949) 679-7777

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **BV** issued **DHQ-19MA2565VTSHPB-A4** and found compliant with the following standards: **FCC Part 15 Subpart B**.

Please be advised,

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

*(1) This device may not cause harmful interference,
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

Signature: 

Signed for and on behalf of: Dahua Technology USA Inc.

Name: Steven Mei

Position: Technical Director