

# FCC Supplier's Declaration of Conformity

**Importer Name:** Dahua Technology USA Inc.

**Importer Address:** 15245 Alton Parkway, Suite 100, Irvine, CA 92618

## Equipment

Product Name: **HDCVI Camera**

Model No.:

DH-HAC-HFW2802TP-Z-A-DP;DH-HAC-HFW2802TN-Z-A-DP;HAC-HFW2802TP-Z-A-DP;HAC-HFW2802TN-Z-A-DP;DH-HAC-HFW2601TP-Z-A-DP;DH-HAC-HFW2601TN-Z-A-DP;HAC-HFW2601TP-Z-A-DP;HAC-HFW2601TN-Z-A-DP;HAC-HFW2802TP-Z-A;HAC-HFW2802TN-Z-A;DH-HAC-HFW2802TP-Z-A;DH-HAC-HFW2802TN-Z-A;A82AF5V;HAC-HFW2601TP-Z-A;HAC-HFW2601TN-Z-A;DH-HAC-HFW2601TP-Z-A;DH-HAC-HFW2601TN-Z-A;HAC-HFW2802TP-A-I8;HAC-HFW2802TN-A-I8;DH-HAC-HFW2802TP-A-I8;DH-HAC-HFW2802TN-A-I8;HAC-HFW2601TP-A-I8;HAC-HFW2601TN-A-I8;DH-HAC-HFW2601TP-A-I8;DH-HAC-HFW2601TN-A-I8;A82AF53;A52AF6Z;HAC-HFW2802TP-Z-A-VP;HAC-HFW2802TN-Z-A-VP;DH-HAC-HFW2802TP-Z-A-VP;DH-HAC-HFW2802TN-Z-A-VP;HAC-HFW2802TP-Z-A-VP-DP;HAC-HFW2802TN-Z-A-VP-DP;DH-HAC-HFW2802TP-Z-A-VP-DP;DH-HAC-HFW2802TN-Z-A-VP-DP;DH-HAC-HFW2802TP-A-I8-VP;DH-HAC-HFW2802TN-A-I8-VP;HAC-HFW2802TP-A-I8-VP;HAC-HFW2802TN-A-I8-VP;HAC-HFW2601TP-Z-A-VP;HAC-HFW2601TN-Z-A-VP;DH-HAC-HFW2601TP-Z-A-VP;DH-HAC-HFW2601TN-Z-A-VP;HAC-HFW2501TP-Z-A;HAC-HFW2501TN-Z-A;DH-HAC-HFW2501TP-Z-A;DH-HAC-HFW2501TN-Z-A;HAC-HFW2501TP-Z-A-DP;HAC-HFW2501TN-Z-A-DP;DH-HAC-HFW2501TP-Z-A-DP;DH-HAC-HFW2501TN-Z-A-DP;HAC-HFW2601TP-Z-A-VP-DP;HAC-HFW2601TN-Z-A-VP-DP;DH-HAC-HFW2601TP-Z-A-VP-DP;DH-HAC-HFW2601TN-Z-A-VP-DP;DH-HAC-HFW2401TP-I8-A;DH-HAC-HFW2401TN-I8-A;HAC-HFW2401TP-I8-A;HAC-HFW2401TN-I8-A;DH-HAC-HFW2401TP-Z-A;DH-HAC-HFW2401TN-Z-A;HAC-HFW2401TP-Z-A;HAC-HFW2401TN-Z-A;DH-HAC-HFW2401TP-Z-A-DP;DH-HAC-HFW2401TN-Z-A-DP;HAC-HFW2401TP-Z-A-DP;HAC-HFW2401TN-Z-A-DP;DH-HAC-HFW2402TP-Z-A;DH-HAC-HFW2402TN-Z-A;HAC-HFW2402TP-Z-A;HAC-HFW2402TN-Z-A;DH-HAC-HFW2402TP-Z-A-DP;DH-HAC-HFW2402TN-Z-A-DP;HAC-HFW2402TP-Z-A-DP;HAC-HFW2402TN-Z-A-DP;DH-HFW2402TP-I8-A;DH-HFW2402TN-I8-A;HFW2402TP-I8-A;HFW2402TN-I8-A;DH-HAC-HFW2501TUP-Z-A;DH-HAC-HFW2501TUN-Z-A;HAC-HFW2501TUP-Z-A;HAC-HFW2501TUN-Z-A;DH-HAC-HFW2802TUP-Z-A;DH-HAC-HFW2802TUN-Z-A;HAC-HFW2802TUP-Z-A;HAC-HFW2802TUN-Z-A;DH-HAC-HFW2401TUP-Z-A;DH-HAC-HFW2401TUN-Z-A;HAC-HFW2401TUP-Z-A;HAC-HFW2401TUN-Z-A;DH-HAC-HFW2402TUP-Z-A;DH-HAC-HFW2402TUN-Z-A;HAC-HFW2402TUP-Z-A;HAC-HFW2402TUN-Z-A;DH-HAC-HFW2241TUP-Z-A;DH-HAC-HFW2241TUN-Z-A;HAC-HFW2241TUP-Z-A;HAC-HFW2241TUN-Z-A;DH-HAC-HFW1200TUP-Z-A;DH-HAC-HFW1200TUN-Z-A;HAC-HFW1200TUP-Z-A;HAC-HFW1200TUN-Z-A;DH-HAC-HFW1230TUP-Z-A;DH-HAC-HFW1230TUN-Z-A;HAC-HFW1230TUP-Z-A;HAC-HFW1230TUN-Z-A;DH-HAC-HFW1231TUP-Z-A;DH-HAC-HFW1231TUN-Z-A;HAC-HFW1231TUP-Z-A;HAC-HFW1231TUN-Z-A;DH-HAC-HFW1400TUP-Z-A;DH-HAC-HFW1400TUN-Z-A;HAC-HFW1400TUP-Z-A;HAC-HFW1400TUN-Z-A;DH-HAC-

HFW1500TUP-Z-A;DH-HAC-HFW1500TUN-Z-A;HAC-HFW1500TUP-Z-A;HAC-HFW1500TUN-Z-A;DH-HAC-HFW1800TUP-Z-A;DH-HAC-HFW1800TUN-Z-A;HAC-HFW1800TUP-Z-A;HAC-HFW1800TUN-Z-A;DH-HAC-HFW1801TUP-Z-A;DH-HAC-HFW1801TUN-Z-A;HAC-HFW1801TUP-Z-A;HAC-HFW1801TUN-Z-A;DH-HAC-HFW2501TUP-Z-A-DP;DH-HAC-HFW2501TUN-Z-A-DP;HAC-HFW2501TUP-Z-A-DP;HAC-HFW2501TUN-Z-A-DP;DH-HAC-HFW2802TUP-Z-A-DP;DH-HAC-HFW2802TUN-Z-A-DP;HAC-HFW2802TUP-Z-A-DP;HAC-HFW2802TUN-Z-A-DP;DH-HAC-HFW2401TUP-Z-A-DP;DH-HAC-HFW2401TUN-Z-A-DP;HAC-HFW2401TUP-Z-A-DP;HAC-HFW2401TUN-Z-A-DP;DH-HAC-HFW2402TUP-Z-A-DP;DH-HAC-HFW2402TUN-Z-A-DP;HAC-HFW2402TUP-Z-A-DP;HAC-HFW2402TUN-Z-A-DP;DH-HAC-HFW2241TUP-Z-A-DP;DH-HAC-HFW2241TUN-Z-A-DP;HAC-HFW2241TUP-Z-A-DP;HAC-HFW2241TUN-Z-A-DP;DH-HAC-HFW1200TUP-Z-A-DP;DH-HAC-HFW1200TUN-Z-A-DP;HAC-HFW1200TUP-Z-A-DP;HAC-HFW1200TUN-Z-A-DP;DH-HAC-HFW1230TUP-Z-A-DP;DH-HAC-HFW1230TUN-Z-A-DP;HAC-HFW1230TUP-Z-A-DP;HAC-HFW1230TUN-Z-A-DP;DH-HAC-HFW1231TUP-Z-A-DP;DH-HAC-HFW1231TUN-Z-A-DP;HAC-HFW1231TUP-Z-A-DP;HAC-HFW1231TUN-Z-A-DP;DH-HAC-HFW1400TUP-Z-A-DP;DH-HAC-HFW1400TUN-Z-A-DP;HAC-HFW1400TUP-Z-A-DP;HAC-HFW1400TUN-Z-A-DP;DH-HAC-HFW1500TUP-Z-A-DP;DH-HAC-HFW1500TUN-Z-A-DP;HAC-HFW1500TUP-Z-A-DP;HAC-HFW1500TUN-Z-A-DP;DH-HAC-HFW1800TUP-Z-A-DP;DH-HAC-HFW1800TUN-Z-A-DP;HAC-HFW1800TUP-Z-A-DP;HAC-HFW1800TUN-Z-A-DP;DH-HAC-HFW1801TUP-Z-A-DP;DH-HAC-HFW1801TUN-Z-A-DP;HAC-HFW1801TUP-Z-A-DP;HAC-HFW1801TUN-Z-A-DP;DH-HAC-HFWabcdTUX-XX-XX-XX-XX;HAC-HFWabcdTUX-XX-XX-XX-XX;

(abcd=0000~9999;X can be P;N or blank;-XX can be -Z;-A;-I8;-I4;-DP;-POC;-LED;-IRE6;-27135 or blank ) DH-HAC-HFW2501TUP-Z-POC;DH-HAC-HFW2501TUN-Z-POC;HAC-HFW2501TUP-Z-POC;HAC-HFW2501TUN-Z-POC;DH-HAC-HFW2802TUP-Z-POC;DH-HAC-HFW2802TUN-Z-POC;HAC-HFW2802TUP-Z-POC;HAC-HFW2802TUN-Z-POC;DH-HAC-HFW2402TUP-Z-POC;DH-HAC-HFW2402TUN-Z-POC;HAC-HFW2402TUP-Z-POC;HAC-HFW2402TUN-Z-POC;DH-HAC-HFW2401TUP-Z-POC;DH-HAC-HFW2401TUN-Z-POC;HAC-HFW2401TUP-Z-POC;HAC-HFW2401TUN-Z-POC;DH-HAC-HFW2241TUP-Z-POC;DH-HAC-HFW2241TUN-Z-POC;HAC-HFW2241TUP-Z-POC;HAC-HFW2241TUN-Z-POC;DH-HAC-HFW1801TUP-Z-POC;DH-HAC-HFW1801TUN-Z-POC;HAC-HFW1801TUP-Z-POC;HAC-HFW1801TUN-Z-POC;DH-HAC-HFW1800TUP-Z-POC;DH-HAC-HFW1800TUN-Z-POC;HAC-HFW1800TUP-Z-POC;HAC-HFW1800TUN-Z-POC;DH-HAC-HFW1500TUP-Z-POC;DH-HAC-HFW1500TUN-Z-POC;HAC-HFW1500TUP-Z-POC;HAC-HFW1500TUN-Z-POC;DH-HAC-HFW1400TUP-Z-POC;DH-HAC-HFW1400TUN-Z-POC;HAC-HFW1400TUP-Z-POC;HAC-HFW1400TUN-Z-POC;DH-HAC-HFW1200TUP-Z-POC;DH-HAC-HFW1200TUN-Z-POC;HAC-HFW1200TUP-Z-POC;HAC-HFW1200TUN-Z-POC;DH-HAC-HFW1231TUP-Z-POC;DH-HAC-HFW1231TUN-Z-POC;HAC-HFW1231TUP-Z-POC;HAC-HFW1231TUN-Z-POC;A52BFAZ;HAC-HFW2241TUP-Z-A-POC-27135-S2;HAC-HFW2241TUN-Z-A-POC-27135-S2;DH-HAC-HFW2241TUP-Z-A-POC-27135-S2;DH-HAC-HFW2241TUN-Z-A-POC-27135-S2;A22DFAZ

Trade Name: 

Telephone. : (949) 679-7777

We, Dahua Technology USA Inc., declare under our sole responsibility that the

above referenced product has been tested on samples according to FCC requirements, for which **SGS** issued **SHEM211201337401** and found compliant with the following standards: **FCC Part 15 Subpart B**.

Please be advised,

*This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:*

*(1) This device may not cause harmful interference,  
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

**Signature:** *Steven Mei*

**Signed for and on behalf of:** Dahua Technology USA Inc.

**Name:** Steven Mei

**Position:** Technical Director