

# FCC Supplier's Declaration of Conformity

**Importer Name:** Dahua Technology USA Inc.

**Importer Address:** 15245 Alton Parkway, Suite 100, Irvine, CA 92618

## Equipment

Product Name: **IP Camera**

Model No.:

DH-IPC-HDBW5241RP-S;DH-IPC-HDBW5241RN-S;IPC-HDBW5241RP-S;IPC-HDBW5241RN-S;DH-IPC-HDBW5241R-S;  
IPC-HDBW5241R-S;IPC-HDBW5241R-S-0280B;IPC-HDBW5241R-S-0360B;IPC-HDBW5241R-S-0600B;DH-IPC-HDBW5241RP-SE;DH-IPC-HDBW5241RN-SE;IPC-HDBW5241RP-SE;IPC-HDBW5241RN-SE;DH-IPC-HDBW5241R-SE;IPC-HDBW5241R-SE;IPC-HDBW5241R-SE-0280B;IPC-HDBW5241R-SE-0360B;IPC-HDBW5241R-SE-0600B;DH-IPC-HDBW5241RP-ASE;DH-IPC-HDBW5241RN-ASE;IPC-HDBW5241RP-ASE;IPC-HDBW5241RN-ASE;DH-IPC-HDBW5241R-ASE;IPC-HDBW5241R-ASE;IPC-HDBW5241R-ASE-0280B;IPC-HDBW5241R-ASE-0360B;IPC-HDBW5241R-ASE-0600B;N25DM62;N25DM63;DH-IPC-HDBW5241RP-ASE-NI;DH-IPC-HDBW5241RN-ASE-NI;IPC-HDBW5241RP-ASE-NI;IPC-HDBW5241RN-ASE-NI;DH-IPC-HDBW5241R-ASE-NI;IPC-HDBW5241R-ASE-NI;DH-IPC-HDBW5241RP-ASE-NI-0360B;IPC-HDBW5241R-ASE-NI-0360B;N25EM63;  
DH-IPC-HDBW5241RN-ASE-NI-0360B-USA;IPC-HDBW5249R-ASE-NI-0360B;DH-IPC-HDBW5442RP-ASE;DH-IPC-HDBW5442RN-ASE;IPC-HDBW5442RP-ASE;IPC-HDBW5442RN-ASE;DH-IPC-HDBW5442R-ASE;IPC-HDBW5442R-ASE;IPC-HDBW5442R-ASE-0280B;IPC-HDBW5442R-ASE-0360B;  
IPC-HDBW5442R-ASE-0600B;N45DM62;N45DM63;DH-IPC-HDBW5442RP-S;DH-IPC-HDBW5442RN-S;  
IPC-HDBW5442RP-S;IPC-HDBW5442RN-S;DH-IPC-HDBW5442R-S;IPC-HDBW5442R-S;IPC-HDBW5442R-S-0280B;  
IPC-HDBW5442R-S-0360B;IPC-HDBW5442R-S-0600B;DH-IPC-HDBW5541RP-S;DH-IPC-HDBW5541RN-S;  
IPC-HDBW5541RP-S;IPC-HDBW5541RN-S;DH-IPC-HDBW5541R-S;IPC-HDBW5541R-S;IPC-HDBW5541R-S-0280B;IPC-HDBW5541R-S-0360B;IPC-HDBW5541R-S-0600B;DH-IPC-HDBW5442RP-SE;DH-IPC-HDBW5442RN-SE;IPC-HDBW5442RP-SE;IPC-HDBW5442RN-SE;DH-IPC-HDBW5442R-SE;IPC-HDBW5442R-SE;IPC-HDBW5442R-SE-0280B;IPC-HDBW5442R-SE-0360B;IPC-HDBW5442R-SE-0600B;DH-IPC-HDBW5541RP-SE;DH-IPC-HDBW5541RN-SE;  
IPC-HDBW5541RP-SE;IPC-HDBW5541RN-SE;DH-IPC-HDBW5541R-SE;IPC-HDBW5541R-SE;IPC-HDBW5541R-SE-0280B;IPC-HDBW5541R-SE-

0360B;IPC-HDBW5541R-SE-0600B;DH-IPC-HDBW5541RP-ASE;DH-IPC-HDBW5541RN-ASE;IPC-HDBW5541RP-ASE;IPC-HDBW5541RN-ASE;DH-IPC-HDBW5541R-ASE;IPC-HDBW5541R-ASE;IPC-HDBW5541R-ASE-0280B;IPC-HDBW5541R-ASE-0360B;IPC-HDBW5541R-ASE-0600B;N55DM62;N55DM63;N85DM62;N85DM64;DH-IPC-HDBW5442RN-ASE-NI;DH-IPC-HDBW5442RP-ASE-NI;IPC-HDBW5442RN-ASE-NI;IPC-HDBW5442RP-ASE-NI;DH-IPC-HDBW5442R-ASE-NI;IPC-HDBW5442R-ASE-NI;DH-IPC-HDBW5442RP-ASE-NI-0360B;IPC-HDBW5442R-ASE-NI-0360B;N45EM63;DH-IPC-HDBW5242RP-ASE-MF;DH-IPC-HDBW5242RN-ASE-MF;IPC-HDBW5242RP-ASE-MF;IPC-HDBW5242RN-ASE-MF;DH-IPC-HDBW5242R-ASE-MF;IPC-HDBW5242R-ASE-MF;IPC-HDBW5242R-ASE-0280B;IPC-HDBW5242R-ASE-0360B;IPC-HDBW5242R-ASE-0600B;DH-IPC-HDBW5242RP-ASE-NI;DH-IPC-HDBW5242RN-ASE-NI;IPC-HDBW5242RP-ASE-NI;IPC-HDBW5242RN-ASE-NI;DH-IPC-HDBW5242R-ASE-NI;IPC-HDBW5242R-ASE-NI;DH-IPC-HDBW5442R-ASE-OPAT;IPC-HDBW5442R-ASE-OPAT;IPC-HDBW5442R-ASE-0280B-OPAT;DH-IPC-HDBW5541R-ASE-OPAT;IPC-HDBW5541R-ASE-OPAT;IPC-HDBW5541R-ASE-0280B-OPAT

Trade Name: 

Telephone. : (949) 679-7777

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **BV** issued **DHQ-19MA2569VTSHPB-A4**, found compliant with the following standards: **FCC Part 15 Subpart B**.

Please be advised,

*This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:*

*(1) This device may not cause harmful interference,  
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

Signature: *Steven Mei*

Signed for and on behalf of: **Dahua Technology USA Inc.**

Name: **Steven Mei**

Position: **Technical Director**