

# FCC Supplier's Declaration of Conformity

**Importer Name:** Dahua Technology USA Inc.  
**Importer Address:** 23 Hubble Irvine, CA 92618

## Equipment

Product Name: **IPC**

Model No.:

DH-IPC-HFW7442HP-Z;DH-IPC-HFW7442HN-Z;IPC-HFW7442HP-Z;IPC-HFW7442HN-Z;  
DH-IPC-HFW7442H-Z;IPC-HFW7442H-Z;IPC-HFW7442H-Z-2712-DC12AC24V;DH-IPC-HFW7842HP-Z;  
DH-IPC-HFW7842HN-Z;IPC-HFW7842HP-Z;IPC-HFW7842HN-Z;DH-IPC-HFW7842H-Z;  
IPC-HFW7842H-Z;IPC-HFW7842H-Z-2712-DC12AC24V;DH-IPC-HFW7442HP-Z4;  
DH-IPC-HFW7442HN-Z4;IPC-HFW7442HP-Z4;IPC-HFW7442HN-Z4;DH-IPC-HFW7442H-Z4;  
IPC-HFW7442H-Z4;DH-IPC-HFW7442HN-ZFR;DH-IPC-HFW7442HP-ZFR;IPC-HFW7442HP-ZFR;  
IPC-HFW7442HN-ZFR;DH-IPC-HFW7442H-ZFR;IPC-HFW7442H-ZFR;DH-IPC-HFW7442HP-Z4FR;  
DH-IPC-HFW7442HN-Z4FR;IPC-HFW7442HP-Z4FR;DH-IPC-HFW7442H-Z4FR;IPC-HFW7442H-Z4FR;  
DH-IPC-HFW5842HP-ZHE;DH-IPC-HFW5842HN-ZHE;IPC-HFW5842HP-ZHE;IPC-HFW5842HN-ZHE;  
DH-IPC-HFW5842H-ZHE;IPC-HFW5842H-ZHE;N85DU7Z;IPC-HFW5842H-ZEH-2712F-DC12AC24V;  
IPC-HFW5842H-ZEH-2712-DC12AC24V;IPC-HFW5842H-ZEH-2712;NK7DU6Z;DH-IPC-HFW71242H-Z;  
IPC-HFW71242H-Z;DH-IPC-HFW71242HP-Z;DH-IPC-HFW71242HN-Z;IPC-HFW71242HP-Z;  
IPC-HFW71242HN-Z;IPC-HFW71242H-ZE-2712-DC12AC24V;IPC-HFW71242H-Z-2712-DC12AC24V;  
IPC-HFW71242H-ZE-2712;IPC-HFW71242H-Z-2712;DH-IPC-HFW71242HP-Z-2712-DC12AC24V;  
DH-IPC-HFW71242HN-Z-2712-DC12AC24V;IPC-HFW71242HP-Z-2712-DC12AC24V;  
IPC-HFW71242HN-Z-2712-DC12AC24V;IPC-HFW7442H-ZE-2712F-DC12AC24V;  
IPC-HFW7442H-ZEH-2712;IPC-HFW7442H-Z-2712F;IPC-HFW7442H-Z4-0832-DC12AC24V;  
IPC-HFW7442H-Z4E-0832-DC12AC24V;IPC-HFW7442H-Z4EH-0832-DC12AC24V;  
IPC-HFW7442H-Z4-0832;IPC-HFW7842H-ZE-2712F-DC12AC24V;IPC-HFW7842H-ZEH-2712;  
IPC-HFW7842H-Z-2712;IPC-HFW7442H-ZFR-2712-DC12AC24V;IPC-HFW7442H-ZFR-2712F-DC12AC24V;  
IPC-HFW7442H-ZFR-2712;IPC-HFW7442H-ZFR-2712F;IPC-HFW7442H-Z4FR-0832-DC12AC24V;  
IPC-HFW7442H-Z4FR-0832;IPC-HFW7842H-Z4-0832-DC12AC24V;IPC-HFW7842H-Z4EH-0832-DC12AC24V;  
IPC-HFW7842H-Z4HE-0832-DC12AC24V;IPC-HFW7842H-Z4E-0832;IPC-HFW5842H-Z4E-0832-DC12AC24V;  
IPC-HFW5842H-Z4HE-0832-DC12AC24V;IPC-HFW5842H-Z4EH-0832-DC12AC24V;  
IPC-HFW5842H-Z4E-0832;N87DU6Z ;DH-IPC-HFW7842HP-Z4;DH-IPC-HFW7842HN-Z4;  
IPC-HFW7842HP-Z4;IPC-HFW7842HN-Z4;DH-IPC-HFW7842H-Z4;IPC-HFW7842H-Z4;  
DH-IPC-HFW5842HP-Z4HE;DH-IPC-HFW5842HN-Z4HE;IPC-HFW5842HP-Z4HE;IPC-HFW5842HN-Z4HE;  
DH-IPC-HFW5842H-Z4HE;IPC-HFW5842H-Z4HE;

Trade Name: 

Telephone. : **(949) 679-7777**

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **BV** issued **DHQA-ESH-P19112904B-A1** and found compliant with the following standards: **FCC Part 15 Subpart B.**

Please be advised,

*This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:*

*(1) This device may not cause harmful interference,  
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

**Signature:**

**Signed for and on behalf of: Dahua Technology USA Inc.**

**Name: Steven Mei**

**Position: Technical Director**