

# FCC Supplier's Declaration of Conformity

Importer Name: Dahua Technology USA Inc.  
Importer Address: 23 Hubble Irvine, CA 92618

## Equipment

Product Name: **IPC**  
Model No.:

DH-IPC-HDBW2431EP-S-S2;DH-IPC-HDBW2431EN-S-S2;  
IPC-HDBW2431EP-S-S2;IPC-HDBW2431EN-S-S2;DH-IPC-HDBW2431E-S-S2;IPC-  
HDBW2431E-S-S2;DH-IPC-HDBW2231EP-S-S2;DH-IPC-HDBW2231EN-S-S2;  
IPC-HDBW2231EP-S-S2;IPC-HDBW2231EN-S-S2;DH-IPC-HDBW2231E-S-S2;IPC-  
HDBW2231E-S-S2;DH-IPC-HDBW2230EP-S-S2;DH-IPC-HDBW2230EN-S-S2;IPC-  
HDBW2230EP-S-S2;IPC-HDBW2230EN-S-S2;DH-IPC-HDBW2230E-S-S2;IPC-  
HDBW2230E-S-S2;DH-IPC-HDBW2531EP-S-S2;DH-IPC-HDBW2531EN-S-S2;IPC-  
HDBW2531EP-S-S2;IPC-HDBW2531EN-S-S2;DH-IPC-HDBW2531E-S-S2;IPC-  
HDBW2531E-S-S2;DH-IPC-HDBW2831EP-S-S2;DH-IPC-HDBW2831EN-S-S2;IPC-  
HDBW2831EP-S-S2;IPC-HDBW2831EN-S-S2;DH-IPC-HDBW2831E-S-S2;IPC-  
HDBW2831E-S-S2;IPC-HDBW1230E-S-0280B-S2;IPC-HDBW1231E-S-0280B-S2;IPC-  
HDBW1431E-S-0280B-S2;IPC-HDBW1531E-S-0280B-S2;IPC-HDBW1831E-S-0280B-  
S2;IPC-HDBW1230E-S-0360B-S2;IPC-HDBW1231E-S-0360B-S2;IPC-HDBW1431E-S-  
0360B-S2;IPC-HDBW1531E-S-0360B-S2;IPC-HDBW1831E-S-0360B-  
S2;N22AL12;N22AL13;N22AL12;N22AL13;N42BL32;N42BL33;N52BL32;N52BL33;N  
82AL32;N82AL33;DE2431-S;DE2531-S;DE2831-S;DH-IPC-HDBW1431EP-S4;DH-  
IPC-HDBW1431EN-S4;IPC-HDBW1431EP-S4;IPC-HDBW1431EN-S4;DH-IPC-  
HDBW1431E-S4;IPC-HDBW1431E-S4;IPC-CD1C40M-0280B;IPC-CD1C40M-  
0360B;DH-IPC-HDBW3441EP-AS;DH-IPC-HDBW3441EN-AS;IPC-HDBW3441EP-  
AS;IPC-HDBW3441EN-AS;DH-IPC-HDBW3441E-AS;IPC-HDBW3441E-AS;DH-IPC-  
HDBW3441EP-S;DH-IPC-HDBW3441EN-S;IPC-HDBW3441EN-S;IPC-HDBW3441EP-  
S;DH-IPC-HDBW3441E-S;IPC-HDBW3441E-S;DH-IPC-HDBW3241EP-AS;DH-IPC-  
HDBW3241EN-AS;IPC-HDBW3241EP-AS;IPC-HDBW3241EN-AS;DH-IPC-  
HDBW3241E-AS;IPC-HDBW3241E-AS;  
DH-IPC-HDBW3241EP-S;DH-IPC-HDBW3241EN-S;IPC-HDBW3241EP-S;IPC-  
HDBW3241EN-S;DH-IPC-HDBW3241E-S;IPC-HDBW3241E-S;DH-IPC-  
HDBW3541EP-AS;DH-IPC-HDBW3541EN-AS;IPC-HDBW3541EP-AS;IPC-  
HDBW3541EN-AS;DH-IPC-HDBW3541E-AS;IPC-HDBW3541E-AS;DH-IPC-  
HDBW3541EP-S;DH-IPC-HDBW3541EN-S;IPC-HDBW3541EP-S;IPC-HDBW3541EN-  
S;DH-IPC-HDBW3541E-S;IPC-HDBW3541E-S;IPC-HDBW3241E-S-0280B;IPC-  
HDBW3241E-AS-0280B;IPC-HDBW3441E-S-0280B;IPC-HDBW3441E-AS-  
0280B;IPC-HDBW3541E-S-0280B;IPC-HDBW3541E-AS-0280B;IPC-HDBW3241E-S-  
0360B;IPC-HDBW3241E-AS-0360B;IPC-HDBW3441E-S-0360B;IPC-HDBW3441E-  
AS-0360B;IPC-HDBW3541E-S-0360B;IPC-HDBW3541E-AS-0360B;IPC-  
HDBW3241E-S-0600B;IPC-HDBW3241E-AS-0600B;IPC-HDBW3441E-S-0600B;IPC-  
HDBW3441E-AS-0600B;IPC-HDBW3541E-S-0600B;IPC-HDBW3541E-AS-  
0600B;N23AL32;N23AL52;N23AL33;N23AL53;N23AL36;N23AL56;N43AL32;N43AL  
52;N43AL33;N43AL53;N43AL36;N43AL56;N53AL32;N53AL52;N53AL33;N53AL53;N  
53AL36;N53AL56;

N43AL52-B;DH-IPC-HDBW3249EP-AS-NI;DH-IPC-HDBW3249EN-AS-NI;IPC-HDBW3249EP-AS-NI;IPC-HDBW3249EN-AS-NI;DH-IPC-HDBW3249E-AS-NI;IPC-HDBW3249E-AS-NI;IPC-HDBW3249E-AS-NI-0280B;IPC-HDBW3249E-AS-NI-0360B; DH-IPC-HDBW3449EP-AS-NI;DH-IPC-HDBW3449EN-AS-NI;IPC-HDBW3449EN-AS-NI; IPC-HDBW3449EP-AS-NI;DH-IPC-HDBW3449E-AS-NI;IPC-HDBW3449E-AS-NI-0280B;IPC-HDBW3449E-AS-NI-0360B;N43BL62;N43BL63

Trade Name: 

Telephone. : (949) 679-7777

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **BV** issued **DHQA-19JY0330VTSHPB-A2** and found compliant with the following standards: **FCC Part 15 Subpart B.**

Please be advised,

*This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:*

*(1) This device may not cause harmful interference,  
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

**Signature:** *Steven Mei*

**Signed for and on behalf of: Dahua Technology USA Inc.**

**Name: Steven Mei**

**Position: Technical Director**