

# FCC Supplier's Declaration of Conformity

**Importer Name:** Dahua Technology USA Inc.

**Importer Address:** 15245 Alton Parkway, Suite 100, Irvine, CA 92618

## Equipment

Product Name: **Network Camera**

Model No.:

"DH-IPC-HFW4241T-AS;DH-IPC-HFW4441T-AS;DH-IPC-HFW4841T-AS;IPC-HFW4241T-AS;IPC-HFW4441T-AS;IPC-HFW4841T-AS;DH-IPC-HFW4241T-ZAS;DH-IPC-HFW4441T-ZAS;DH-IPC-HFW4841T-ZAS;IPC-HFW4241T-ZAS;IPC-HFW4441T-ZAS;IPC-HFW4841T-ZAS;DH-IPC-HFW4241T-AS-0360B;DH-IPC-HFW4241T-AS-0600B;DH-IPC-HFW4241T-AS-0800B;DH-IPC-HFW4441T-AS-0360B;DH-IPC-HFW4441T-AS-0600B;DH-IPC-HFW4441T-AS-0800B;DH-IPC-HFW4841T-AS-0360B;DH-IPC-HFW4841T-AS-0600B;DH-IPC-HFW4841T-AS-0800B;IPC-HFW4241T-AS-0360B;IPC-HFW4241T-AS-0600B;IPC-HFW4241T-AS-0800B;IPC-HFW4441T-AS-0360B;IPC-HFW4441T-AS-0600B;IPC-HFW4441T-AS-0800B;IPC-HFW4841T-AS-0360B;IPC-HFW4841T-AS-0600B;IPC-HFW4841T-AS-0800B;DH-IPC-HFW4241T-ZAS-27135;DH-IPC-HFW4441T-ZAS-27135;DH-IPC-HFW4841T-ZAS-27135;IPC-HFW4241T-ZAS-27135;IPC-HFW4441T-ZAS-27135;IPC-HFW4841T-ZAS-27135;DH-IPC-HFW3241T-AS-S2;DH-IPC-HFW3441T-AS-S2;DH-IPC-HFW3841T-AS-S2;IPC-HFW3241T-AS-S2;IPC-HFW3441T-AS-S2;IPC-HFW3841T-AS-S2;DH-IPC-HFW3241T-ZAS-S2;DH-IPC-HFW3441T-ZAS-S2;DH-IPC-HFW3841T-ZAS-S2;IPC-HFW3241T-ZAS-S2;IPC-HFW3441T-ZAS-S2;IPC-HFW3841T-ZAS-S2;DH-IPC-HFW3241T-AS-0360B-S2;DH-IPC-HFW3241T-AS-0600B-S2;DH-IPC-HFW3241T-AS-0800B-S2;DH-IPC-HFW3441T-AS-0360B-S2;DH-IPC-HFW3441T-AS-0600B-S2;DH-IPC-HFW3441T-AS-0800B-S2;DH-IPC-HFW3841T-AS-0360B-S2;DH-IPC-HFW3841T-AS-0600B-S2;DH-IPC-HFW3841T-AS-0800B-S2;IPC-HFW3241T-AS-0360B-S2;IPC-HFW3241T-AS-0600B-S2;IPC-HFW3241T-AS-0800B-S2;IPC-HFW3441T-AS-0360B-S2;IPC-HFW3441T-AS-0600B-S2;IPC-HFW3441T-AS-0800B-S2;IPC-HFW3841T-AS-0360B-S2;IPC-HFW3841T-AS-0600B-S2;IPC-HFW3841T-AS-0800B-S2;DH-IPC-HFW3241T-ZAS-27135-S2;DH-IPC-HFW3441T-ZAS-27135-S2;DH-IPC-HFW3841T-ZAS-27135-S2;IPC-HFW3241T-ZAS-27135-S2;IPC-HFW3441T-ZAS-27135-S2;IPC-HFW3841T-ZAS-27135-S2;N24DF62;N24DF63;N24DF66;N44DF62;N44DF63;N44DF66;N84DF62;N84DF63;N84DF66;N24DF6Z;N44DF6Z;N84DF6Z  
DH-IPC-HFW3541T-AS-S2;IPC-HFW3541T-AS-S2;DH-IPC-HFW3541T-ZAS-S2;IPC-HFW3541T-ZAS-S2;DH-IPC-HFW3541T-AS-0360B-S2;DH-IPC-HFW3541T-AS-0600B-S2;DH-IPC-HFW3541T-AS-0800B-S2;IPC-HFW3541T-AS-0360B-S2;IPC-HFW3541T-AS-0600B-S2;IPC-HFW3541T-AS-0800B-S2;DH-IPC-HFW3541T-ZAS-27135-S2;IPC-HFW3541T-ZAS-27135-S2;N45DF62;N45DF63;N45DF66;N54DF6Z;DH-IPC-HFW3641T-ZAS-S2;IPC-HFW3641T-ZAS-S2;DH-IPC-HFW4541TP-ZAS;IPC-HFW4541TP-ZAS;DH-IPC-HFW4541T-AS;IPC-HFW4541T-AS;Na4DFbcd;DH-IPC-HFW3641T-ZAS-27135-S2-AUS;IPC-HFW3641T-ZAS-27135-S2-AUS;DH-IPC-HFW4541T-ZAS-27135;IPC-HFW4541T-ZAS-27135;DH-IPC-HFW4541T-AS-0360B;DH-IPC-HFW4541T-AS-

0600B;DH-IPC-HFW4541T-AS-0800B;IPC-HFW4541T-AS-0360B;IPC-HFW4541T-AS-0600B;IPC-HFW4541T-AS-0800B;DH-IPC-HFW3666TP-ZAS-AUS;DH-IPC-HFW3666T-ZAS-AUS;IPC-HFW3666T-ZAS-AUS;DH-IPC-HFW3466TP-ZAS-AUS;DH-IPC-HFW3466T-ZAS-AUS;IPC-HFW3466T-ZAS-AUS;DH-IPC-HFW3866TP-ZAS-AUS;DH-IPC-HFW3866T-ZAS-AUS;IPC-HFW3866T-ZAS-AUS;DH-IPC-HFW4541T-ZAS;IPC-HFW4541T-ZAS;DH-IPC-HFW3466TP-AS-P;DH-IPC-HFW3466T-AS-P;IPC-HFW3466T-AS-P"

Trade Name: 

Telephone. : (949) 679-7777

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **UL** issued **4790446379-3-2-1-S** and found compliant with the following standards: **FCC Part 15 Subpart B**.

Please be advised,

*This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:*

*(1) This device may not cause harmful interference,  
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

**Signature:** *Steven Mei*

**Signed for and on behalf of: Dahua Technology USA Inc.**

**Name: Steven Mei**

**Position: Technical Director**