

FCC Supplier's Declaration of Conformity

Importer Name: Dahua Technology USA Inc.

Importer Address: 15245 Alton Parkway, Suite 100, Irvine, CA 92618

Equipment

Product Name: **Network Camera**

Model No.:

DH-IPC-HDW2249TP-S-IL-0280B;DH-IPC-HDW2249TN-S-IL-0280B;DH-IPC-HDW2249T-S-IL-0280B;DH-IPC-HDW2249T-S-IL;DH-IPC-HDW2249TP-S-IL-0360B;DH-IPC-HDW2449T-S-IL;DH-IPC-HDW2249TN-S-IL-0360B;DH-IPC-HDW2249T-S-IL-0360B;IPC-HDW2249T-S-IL-0280B;DH-IPC-HDW2449TP-S-IL-0280B;DH-IPC-HDW2449TN-S-IL-0280B;IPC-HDW2249TN-S-IL-0360B;DH-IPC-HDW2449T-S-IL-0280B;DH-IPC-HDW2449TP-S-IL-0360B;IPC-HDW2249TP-S-IL-0280B;DH-IPC-HDW2449TN-S-IL-0360B;DH-IPC-HDW2449T-S-IL-0360B;IPC-HDW2249TN-S-IL-0280B;IPC-HDW2249TP-S-IL-0360B;IPC-HDW2449TP-S-IL-0360B;IPC-HDW2449TN-S-IL-0360B;IPC-HDW2249T-S-IL-0360B;IPC-HDW2249T-S-IL;IPC-HDW2449TP-S-IL-0280B;IPC-HDW2449T-S-IL-0360B;IPC-HDW2449TN-S-IL-0280B;IPC-HDW2449T-S-IL-0280B;IPC-HDW2449T-S-IL;DH-IPC-HDW2249TMP-S-IL-0280B;DH-IPC-HDW2249TMP-S-IL-0360B;DH-IPC-HDW2449TMP-S-IL-0280B;DH-IPC-HDW2449TMP-S-IL-0360B;DH-IPC-HDW2549TMP-S-IL-0280B;DH-IPC-HDW2549TMP-S-IL-0360B;DH-IPC-HDW2849TMP-S-IL-0280B;DH-IPC-HDW2849TMP-S-IL-0360B;IPC-HDW2249TMP-S-IL-0280B;IPC-HDW2249TMP-S-IL-0360B;IPC-HDW2449TMP-S-IL-0280B;IPC-HDW2449TMP-S-IL-0360B;IPC-HDW2549TMP-S-IL-0280B;IPC-HDW2549TMP-S-IL-0360B;IPC-HDW2849TMP-S-IL-0280B;IPC-HDW2849TMP-S-IL-0360B;DH-IPC-HDW2249TMN-S-IL-0280B;DH-IPC-HDW2249TMN-S-IL-0360B;DH-IPC-HDW2449TMN-S-IL-0280B;DH-IPC-HDW2449TMN-S-IL-0360B;DH-IPC-HDW2549TMN-S-IL-0280B;DH-IPC-HDW2549TMN-S-IL-0360B;DH-IPC-HDW2849TMN-S-IL-0280B;DH-IPC-HDW2849TMN-S-IL-0360B;IPC-HDW2249TMN-S-IL-0280B;IPC-HDW2249TMN-S-IL-0360B;IPC-HDW2449TMN-S-IL-0280B;IPC-HDW2449TMN-S-IL-0360B;IPC-HDW2549TMN-S-IL-0280B;IPC-HDW2549TMN-S-IL-0360B;IPC-HDW2849TMN-S-IL-0280B;IPC-HDW2849TMN-S-IL-0360B;DH-IPC-HDW2249TM-S-IL;DH-IPC-HDW2249TM-S-IL DH-IPC-HDW2449TM-S-IL;DH-IPC-HDW2449TM-S-IL;DH-IPC-HDW2549TM-S-IL;DH-IPC-HDW2549TM-S-IL;DH-IPC-HDW2849TM-S-IL;DH-IPC-HDW2849TM-S-IL;IPC-HDW2249TM-S-IL;IPC-HDW2249TM-S-IL;IPC-HDW2449TM-S-IL;IPC-HDW2449TM-S-IL;IPC-HDW2449TM-S-IL;IPC-HDW2549TM-S-IL;IPC-HDW2549TM-S-IL;IPC-HDW2849TM-S-IL;IPC-HDW2849TM-S-IL;DH-IPC-HDW2249TMP-S-IL-0280B-USA;DH-IPC-HDW2249TMP-S-IL-0360B-USA;DH-IPC-HDW2449TMP-S-IL-0280B-USA;DH-IPC-HDW2449TMP-S-IL-0360B-USA;DH-IPC-HDW2549TMP-S-IL-0280B-USA;DH-IPC-HDW2549TMP-S-IL-0360B-USA;DH-IPC-HDW2849TMP-S-IL-0280B-USA;DH-IPC-HDW2849TMP-S-IL-0360B-USA;DH-IPC-HDW2249TMN-S-IL-0280B-USA;DH-IPC-HDW2249TMN-S-IL-0360B-USA;DH-IPC-HDW2449TMN-S-IL-0280B-USA;DH-IPC-HDW2449TMN-S-IL-0360B-USA;DH-IPC-HDW2549TMN-S-IL-0280B-USA;DH-IPC-HDW2549TMN-S-IL-0360B-USA;DH-IPC-HDW2849TMN-S-IL-0280B-USA;DH-IPC-HDW2849TMN-S-IL-0360B-USA;Na2DJbcd;DH-IPC-HDW2249TM-S-IL-

0280B;DH-IPC-HDW2249TM-S-IL-0360B;DH-IPC-HDW2449TM-S-IL-0280B;DH-IPC-HDW2449TM-S-IL-0360B;DH-IPC-HDW2549TM-S-IL-0280B;DH-IPC-HDW2549TM-S-IL-0360B;DH-IPC-HDW2849TM-S-IL-0280B;DH-IPC-HDW2849TM-S-IL-0360B;IPC-HDW2249TM-S-IL-0280B;IPC-HDW2249TM-S-IL-0360B;IPC-HDW2449TM-S-IL-0280B;IPC-HDW2449TM-S-IL-0360B;IPC-HDW2549TM-S-IL-0280B;IPC-HDW2549TM-S-IL-0360B;IPC-HDW2849TM-S-IL-0280B;IPC-HDW2849TM-S-IL-0360B

Trade Name: 

Telephone. : (949) 679-7777

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **UL** issued **4790479673-2-2** and found compliant with the following standards: **FCC Part 15 Subpart B**.

Please be advised,

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

*(1) This device may not cause harmful interference,
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

Signature: *Steven Mei*

Signed for and on behalf of: Dahua Technology USA Inc.

Name: Steven Mei

Position: Technical Director