

# FCC Supplier's Declaration of Conformity

**Importer Name:** Dahua Technology USA Inc.

**Importer Address:** 15245 Alton Parkway, Suite 100, Irvine, CA 92618

## Equipment

Product Name: **Network Camera**

Model No.:

DH-IPC-HFW2431TP-ZAS-S2;DH-IPC-HFW2431TN-ZAS-S2;IPC-HFW2431TP-ZAS-S2;IPC-HFW2431TN-ZAS-S2;DH-IPC-HFW2431T-ZAS-S2;IPC-HFW2431T-ZAS-S2;DH-IPC-HFW2431TP-ZS-S2;DH-IPC-HFW2431TN-ZS-S2;IPC-HFW2431TP-ZS-S2;IPC-HFW2431TN-ZS-S2;DH-IPC-HFW2431T-ZS-S2;IPC-HFW2431T-ZS-S2;DH-IPC-HFW2231TP-ZAS-S2;DH-IPC-HFW2231TN-ZAS-S2;IPC-HFW2231TP-ZAS-S2;IPC-HFW2231TN-ZAS-S2;DH-IPC-HFW2231T-ZAS-S2;IPC-HFW2231T-ZAS-S2;DH-IPC-HFW2231TP-ZS-S2;DH-IPC-HFW2231TN-ZS-S2;IPC-HFW2231TP-ZS-S2;IPC-HFW2231TN-ZS-S2;DH-IPC-HFW2231T-ZS-S2;IPC-HFW2231T-ZS-S2;DH-IPC-HFW2531TP-ZAS-S2;DH-IPC-HFW2531TN-ZAS-S2;IPC-HFW2531TP-ZAS-S2;IPC-HFW2531TN-ZAS-S2;DH-IPC-HFW2531T-ZAS-S2;IPC-HFW2531T-ZAS-S2;DH-IPC-HFW2531TP-ZS-S2;DH-IPC-HFW2531TP-ZS-S2;IPC-HFW2531TP-ZS-S2;IPC-HFW2531TP-ZS-S2;DH-IPC-HFW2531T-ZS-S2;IPC-HFW2531T-ZS-S2;DH-IPC-HFW2831TP-ZAS-S2;DH-IPC-HFW2831TN-ZAS-S2;IPC-HFW2831TP-ZAS-S2;IPC-HFW2831TN-ZAS-S2;DH-IPC-HFW2831T-ZAS-S2;IPC-HFW2831T-ZAS-S2;DH-IPC-HFW2831TP-ZS-S2;DH-IPC-HFW2831TP-ZS-S2;IPC-HFW2831TP-ZS-S2;IPC-HFW2831TP-ZS-S2;DH-IPC-HFW2831T-ZS-S2;IPC-HFW2831T-ZS-S2;IPC-HFW2231T-ZS-27135-S2;IPC-HFW2231T-ZS-27135;IPC-HFW2231T-ZAS-27135-S2;IPC-HFW2231T-ZAS-27135;IPC-HFW2431T-ZS-27135-S2;IPC-HFW2431T-ZS-27135;IPC-HFW2431T-ZAS-27135-S2;IPC-HFW2431T-ZAS-27135;IPC-HFW2531T-ZS-27135-S2;IPC-HFW2531T-ZS-27135;IPC-HFW2531T-ZAS-27135-S2;IPC-HFW2531T-ZAS-27135;IPC-HFW2831T-ZS-27135-S2;IPC-HFW2831T-ZS-27135;IPC-HFW2831T-ZAS-27135-S2;IPC-HFW2831T-ZAS-27135;N22AF3Z;N22AF6Z;N42BF3Z;N42BF6Z;N52BFAZ;N52BF6Z;N82AF3Z;N82AF5Z;BT2431-ZS;BT2531-ZS;BT2831-ZAS;DH-IPC-HFW1431TP-ZS-S4;DH-IPC-HFW1431TN-ZS-S4;IPC-HFW1431TP-ZS-S4;IPC-HFW1431TN-ZS-S4;DH-IPC-HFW1431T-ZS-S4;IPC-HFW1431T-ZS-S4;DH-IPC-HFW1230TP-ZS-S4;DH-IPC-HFW1230TN-ZS-S4;IPC-HFW1230TP-ZS-S4;IPC-HFW1230TN-ZS-S4;DH-IPC-HFW1230T-ZS-S4;IPC-HFW1230T-ZS-S4;DH-IPC-HFW3241TP-ZS;DH-IPC-HFW3241TN-ZS;IPC-HFW3241TP-ZS;IPC-HFW3241TN-ZS;DH-IPC-HFW3241T-ZS;IPC-HFW3241T-ZS;DH-IPC-HFW3241TP-ZAS;DH-IPC-HFW3241TN-ZAS;IPC-HFW3241TP-ZAS;IPC-HFW3241TN-ZAS;DH-IPC-HFW3241T-ZAS;IPC-HFW3241T-ZAS;DH-IPC-HFW3441TP-ZS;DH-IPC-HFW3441TN-ZS;IPC-HFW3441TP-ZS;IPC-HFW3441TN-ZS;DH-IPC-HFW3441T-ZS;IPC-HFW3441T-ZS;DH-IPC-HFW3441TP-ZAS;DH-IPC-HFW3441TN-ZAS;IPC-HFW3441TP-ZAS;IPC-HFW3441TN-ZAS;DH-IPC-HFW3441T-ZAS;IPC-HFW3441T-ZAS;DH-IPC-HFW3541TP-ZS;DH-IPC-HFW3541TN-ZS;IPC-HFW3541TP-ZS;IPC-HFW3541TN-ZS;DH-IPC-HFW3541T-ZS;IPC-HFW3541T-ZS;DH-IPC-HFW3541TP-ZAS;DH-IPC-HFW3541TN-ZS;IPC-HFW3541TP-ZAS;IPC-HFW3541TN-ZAS;DH-IPC-HFW3541T-ZS;IPC-HFW3541T-

ZAS;IPC-HFW3241T-ZS-27135;IPC-HFW3241T-ZAS-27135;IPC-HFW3441T-ZS-27135;IPC-HFW3441T-ZAS-27135;IPC-HFW3541T-ZS-27135;IPC-HFW3541T-ZAS-27135;N23AF3Z;N23AF5Z;N43AF3Z;N43AF5Z;N53AF3Z;N53AF5Z;DH-IPC-HFW1231T-ZAS-S2;DH-IPC-HFW2541T-ZS;DH-IPC-HFW2541T-ZAS;IPC-HFW2541T-ZS;IPC-HFW2541T-ZAS;DH-IPC-HFW2541T-ZS-27135;DH-IPC-HFW2541T-ZAS-27135;IPC-HFW2541T-ZS-27135;IPC-HFW2541T-ZAS-27135

Trade Name: 

Telephone. : (949) 679-7777

We, **Dahua Technology USA Inc.**, declare under our sole responsibility that the above referenced product has been tested on samples according to FCC requirements, for which **BV** issued **DHQA-19JY0328VTSHPB-A2** and found compliant with the following standards: **FCC Part 15 Subpart B.**

Please be advised,

*This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:*

*(1) This device may not cause harmful interference,  
And (2) this device must accept any interference received, including Interference that may cause undesirable operation.*

**Signature:** *Steven Mei*

**Signed for and on behalf of: Dahua Technology USA Inc.**

**Name: Steven Mei**

**Position: Technical Director**